

Salisbury City Council
The Guildhall
Market Place
Salisbury
Wiltshire
SP1 1JH



Bawden Tree Care

Unit 1
Mills Way Centre
Amesbury
Wiltshire
SP4 7AU

Phone: 01980 623015

info@bawdentreecare.co.uk

General Tree Assessment (Detailed)

Tree ID: G1 A Group
--

Tag: **Assessor:** Alex Pearce
TPO: **Date:** 26-Sep-19

Tree Comment:
Survey Comment: Group of 3 trees x2 Hollies and a silver birch. All trees are leaning towards car park and may need a height reduction at some point

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	12 m		4	300 mm	Mature			N/A	26-Sep-21	Fair
Observations	Root			Stem			Branch			Leaf/Bud
	No visual defects			Old pruning wounds			Minor dead wood			Normal
Work	Category			Action					Priority	Done
	See Comment			Unspecified						No

Tree ID: T1 Sycamore
Acer pseudoplatanus

Tag: **Assessor:** Alex Pearce
TPO: **Date:** 26-Sep-19

Tree Comment:
Survey Comment:

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	20 m		2	1000 mm	Mature			N/A	26-Sep-22	Fair
Observations	Root			Stem			Branch			Leaf/Bud
	No visual defects			Old pruning wounds			Minor dead wood Major dead wood Old pruning wounds			Normal
Work	Category			Action					Priority	Done
	No action			Unspecified						No

General Tree Assessment (Detailed)

Tree ID: T2		Common Beech <i>Fagus sylvatica</i>			Tag: 7606 TPO:			Assessor: Alex Pearce Date: 26-Sep-19			
Tree Comment:											
Survey Comment: Meripilus in and around buttress roots											
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		20 m		1	1500 mm	Over Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		Fungus or decay Damage to buttress roots			Cracked / included bark Old pruning wounds		Minor dead wood Old pruning wounds		Normal		
Work		Category			Action		Priority			Done	
		Further inspection			Climb and inspect		6 Months			No	

Tree ID: T3		Lawson Cypress <i>Chamaecyparis lawsoniana</i>			Tag: TPO:		Assessor: Alex Pearce Date: 26-Sep-19				
		Tree Comment:			Survey Comment: Re inspect in next survey						
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		15 m		4	750 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			Bark wounds Old pruning wounds		Minor dead wood		Normal		
Work		Category			Action		Priority			Done	
		Re-inspect			Unspecified					No	

General Tree Assessment (Detailed)

Tree ID: T4		Wellingtonia <i>Sequoiadendron giganteum</i>				Tag: TPO:		Assessor: Alex Pearce Date: 26-Sep-19			
						Tree Comment:					
						Survey Comment:					
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		20 m		1	1500 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			Old pruning wounds Ivy covered		Minor dead wood Major dead wood		Normal		
Work		Category			Action				Priority		Done
		Ivy			Sever/remove ivy				6 Months		No

Tree ID: T5		Western Hemlock <i>Tsuga heterophylla</i>				Tag: 7609 TPO:			Assessor: Alex Pearce Date: 26-Sep-19		
Tree Comment:											
Survey Comment:											
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		17 m		1	450 mm	Semi-mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch			Leaf/Bud	
		No visual defects			Old pruning wounds		Minor dead wood			Normal	
Work		Category			Action			Priority			Done
		No action			Unspecified						No

General Tree Assessment (Detailed)

Tree ID: T6	Common Beech <i>Fagus sylvatica</i>		Tag:		Assessor: Alex Pearce	
			TPO:		Date: 26-Sep-19	
			Tree Comment:			
			Survey Comment: Cable bracing present in crown some has broken. Recommend aerial inspection and possibly replace broken bracing.			
Details	Height	Spread	Stems	Ø	Maturity	Condition
	20 m		3	1500 mm	Over Mature	Fair
Observations	Root	Stem		Branch		Leaf/Bud
	No visual defects	Old pruning wounds Weak fork Tight union		Minor dead wood Old pruning wounds Cable / rod brace present		Normal
Work	Category	Action		Priority		Done
	Further inspection	Climb and inspect		6 Months		No

Tree ID: T7	Cedar of Lebanon <i>Cedrus libani</i>		Tag: 7611		Assessor: Alex Pearce	
			TPO:		Date: 26-Sep-19	
			Tree Comment:			
			Survey Comment:			
Details	Height	Spread	Stems	Ø	Maturity	Condition
	20 m		1	1250 mm	Mature	Fair
Observations	Root	Stem		Branch		Leaf/Bud
	No visual defects	Old pruning wounds		Minor dead wood Major dead wood Old pruning wounds		Normal
Work	Category	Action		Priority		Done
	Remove	Major dead wood		1 year		No

General Tree Assessment (Detailed)

Tree ID: T8		Common Beech <i>Fagus sylvatica</i>				Tag:		Assessor: Alex Pearce			
						TPO:		Date: 26-Sep-19			
						Tree Comment:					
						Survey Comment:		Tree has been Pollarded in the past approximately 30 years ago re growth should be reduced at some point in the next 2 years			
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		17 m		4	1000 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root	Stem			Branch			Leaf/Bud		
		No visual defects	Old pruning wounds Epicormic growths Tight union			Minor dead wood Old pruning wounds Witches broom Epicormic growths			Normal		
Work		Category	Action						Priority		Done
		See Comment	Unspecified								No

Tree ID: T9		Unknown		Tag:		Assessor: Alex Pearce					
		- -		TPO:		Date: 26-Sep-19					
				Tree Comment:							
				Survey Comment: Fell dead small tree							
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		3 m		1	45 mm	Dead			N/A	26-Dec-20	
Observations		Root			Stem			Branch		Leaf/Bud	
		No visual defects								All dead / absent	
Work		Category			Action					Priority	Done
		Fell			Fell to ground level					3 Months	No

General Tree Assessment (Detailed)

Tree ID: T10		Plum <i>Prunus Domestica</i>		Tag: TPO:		Assessor: Alex Pearce Date: 26-Sep-19					
		Tree Comment: Survey Comment: Tree has major decay around old pruning wound near base of stem towards road if stem is removed it will unbalance the tree would recommend to fell tree in the next 2-3 years									
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		5 m		3	300 mm	Mature			N/A	26-Sep-21	Poor
Observations		Root		Stem		Branch		Leaf/Bud			
		No visual defects		Fungus or decay Old pruning wounds		Damage / wounding Minor dead wood		Normal			
Work		Category		Action				Priority		Done	
		See Comment		Unspecified						No	

Tree ID: T11		Plum <i>Prunus Domestica</i>		Tag: TPO:		Assessor: Alex Pearce Date: 26-Sep-19				
		Tree Comment: Survey Comment:								
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	3 m		1	70 mm	Young			N/A	26-Sep-21	Good
Observations	Root			Stem			Branch			Leaf/Bud
	No visual defects			No visual defect		No visual defects				Normal
Work	Category			Action					Priority	Done
	No action			Unspecified						No

General Tree Assessment (Detailed)

Tree ID: T12	Common Beech <i>Fagus sylvatica</i>		Tag:		Assessor: Alex Pearce	
			TPO:		Date: 26-Sep-19	
			Tree Comment:			
			Survey Comment: Aerial inspection of crown break recommended			
Details	Height	Spread	Stems	Ø	Maturity	Condition
	20 m		1	750 mm	Mature	Fair
Observations	Root	Stem		Branch		Leaf/Bud
	No visual defects	Old pruning wounds Weak fork		Minor dead wood Old pruning wounds		Normal
Work	Category	Action		Priority		Done
	Further inspection	Climb and inspect		6 Months		No

Tree ID: T13	Scots Pine <i>Pinus sylvestris</i>		Tag: 7614		Assessor: Alex Pearce	
			TPO:		Date: 26-Sep-19	
			Tree Comment:			
			Survey Comment:			
Details	Height	Spread	Stems	Ø	Maturity	Condition
	18 m		1	500 mm	Mature	Fair
Observations	Root	Stem		Branch		Leaf/Bud
	No visual defects	Old pruning wounds		Minor dead wood Major dead wood		Normal
Work	Category	Action		Priority		Done
	No action	Unspecified				No

General Tree Assessment (Detailed)

Tree ID: T14		Red Horse Chestnut <i>Aesculus carnea</i>				Tag: 7613 TPO:		Assessor: Alex Pearce Date: 26-Sep-19			
Tree Comment:											
Survey Comment: Burs on main stem and in lower crown											
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		15 m		1	500 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			Old pruning wounds		Minor dead wood Old pruning wounds		Normal		
Work		Category			Action				Priority		Done
		No action			Unspecified						No

Tree ID: T15		Common Holly <i>Ilex aquifolium</i>				Tag: 7616 TPO:			Assessor: Alex Pearce Date: 26-Sep-19	
Tree Comment: Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m		2	300 mm	Mature			N/A	26-Sep-21	Fair
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			Bifurcated Tight union		Minor dead wood		Normal		
Work	Category			Action		Priority				Done
	No action			Unspecified						No

Tree ID: T16		Scots Pine <i>Pinus sylvestris</i>		Tag: 7617 TPO:		Assessor: Alex Pearce Date: 26-Sep-19				
Tree Comment: Survey Comment: Tree is 90% dead and is just in falling distance of the road recommended to fell										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	16 m		1	400 mm	Dead			N/A	26-Dec-20	Dangerous
Observations	Root			Stem			Branch			Leaf/Bud
	No visual defects									
Work	Category			Action				Priority	Done	
	Fell			Fell to ground level				3 Months	No	

Page 8

General Assessment

TreeMinder

11/02/2020

General Tree Assessment (Detailed)

Tree ID: T17		Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: 7622		Assessor: Alex Pearce				
						TPO:		Date: 26-Sep-19				
						Tree Comment:						
						Survey Comment:						
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition	
		166 m		2	450 mm	Semi-mature			N/A	26-Sep-21	Fair	
Observations		Root			Stem		Branch		Leaf/Bud			
		No visual defects			Bifurcated		No visual defects		Normal			
Work		Category			Action						Priority	Done
		No action			Unspecified							No

Tree ID: T18		Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: 7624		Assessor: Alex Pearce			
						TPO:		Date: 26-Sep-19			
						Tree Comment:					
						Survey Comment:		Reduce crown by 2-3m to reduce stress on poor union			
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		17 m		3	500 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			Old pruning wounds Trifurcated Tight union		Minor dead wood Old pruning wounds		Normal		
Work		Category			Action				Priority		Done
		Reduce crown(s)			By 20%				1 year		No

General Tree Assessment (Detailed)

Tree ID: T19	Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: TPO: Tree Comment: Survey Comment: Reduce crown by 2-3m				Assessor: Alex Pearce Date: 26-Sep-19	
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	18 m		3	1250 mm	Mature			N/A	26-Sep-21	Fair
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Ivy covered		Minor dead wood Old pruning wounds		Normal			
Work	Category		Action				Priority		Done	
	Ivy		Sever/remove ivy				3 Months		No	
	Reduce crown(s)		By 20%				1 year		No	

Tree ID: T20	Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: 7626 TPO: Tree Comment: Survey Comment: Reduce crown by 2-3m				Assessor: Alex Pearce Date: 26-Sep-19	
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	18 m		2	1000 mm	Mature			N/A	26-Sep-21	Fair
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Old pruning wounds		Minor dead wood Old pruning wounds		Normal			
Work	Category		Action				Priority		Done	
	Reduce crown(s)		By 20%				1 year		No	

General Tree Assessment (Detailed)

Tree ID: T21		Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: 7627 TPO:		Assessor: Alex Pearce Date: 26-Sep-19			
Tree Comment:											
Survey Comment: Tree is a lapsed pollard recommend to reduce regrowth by 3m											
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		17 m		2	750 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			Old pruning wounds		Minor dead wood Old pruning wounds		Normal		
Work		Category			Action					Priority	Done
		Reduce crown(s)			By 25%					1 year	No

Tree ID: T22		Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: 7629 TPO:		Assessor: Alex Pearce Date: 26-Sep-19			
Tree Comment:											
Survey Comment: Tree is a lapsed pollard recommend to reduce regrowth by 3m											
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		18 m		5	1000 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			Old pruning wounds		Minor dead wood Old pruning wounds		Normal		
Work		Category			Action		Priority			Done	
		Reduce crown(s)			By 25%		1 year			No	

General Tree Assessment (Detailed)

Tree ID: T23		Common Horse Chestnut <i>Aesculus hippocastanum</i>				Tag: 7630 TPO:		Assessor: Alex Pearce Date: 26-Sep-19			
Tree Comment: Survey Comment: Tree is a lapsed pollard would recommend to reduce crown by 3-4m. Buttress also has multiple nails in it from vandalism											
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		19 m		1	1000 mm	Mature			N/A	26-Sep-21	Fair
Observations		Root		Stem		Branch			Leaf/Bud		
		No visual defects		Bark wounds Old pruning wounds		Minor dead wood Old pruning wounds Cavities			Normal		
Work		Category		Action					Priority		Done
		Reduce crown(s)		By 25%					1 year		No

Tree ID: T24	Common Horse Chestnut <i>Aesculus hippocastanum</i>					Tag: 7631 TPO:		Assessor: Alex Pearce Date: 26-Sep-19		
	Tree Comment:									
	Survey Comment: Tree is a lapsed pollard with Ganoderma applanatum/australe at the base recommend to reduce crown after results from picus report reduction size to be determined after report									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	18 m		4	1250 mm	Mature			N/A	26-Sep-21	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	Fungus or decay			Old pruning wounds		Minor dead wood Old pruning wounds			Normal	
Work	Category			Action				Priority		Done
	Further inspection			On internal trunk decay.				6 Months		No
	Reduce crown(s)			By 25%				1 year		No

General Tree Assessment (Detailed)

Tree ID: T25

Red Horse Chestnut
Aesculus carnea

Tag:

TPO:

Tree Comment:

Survey Comment:

Assessor: Alex Pearce

Date: 26-Sep-19

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m		1	750 mm	Mature			N/A	26-Dec-20	Fair
Observations	Root	Stem				Branch			Leaf/Bud	
	No visual defects	Fungus or decay Old pruning wounds Ivy covered				Minor dead wood Old pruning wounds			Normal	
Work	Category	Action				Priority			Done	
	Ivy	Sever/remove ivy				6 Months			No	
	Re-inspect	Once ivy removed							No	

Tree ID: T26

Silver Birch
Betula pendula

Tag:

TPO:

Tree Comment:

Survey Comment:

Assessor: Alex Pearce

Date: 26-Sep-19

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	15 m		1	750 mm	Mature			N/A	26-Sep-21	Fair
Observations	Root	Stem				Branch			Leaf/Bud	
	No visual defects	Ivy covered				Minor dead wood			Normal	
Work	Category	Action				Priority			Done	
	Ivy	Sever/remove ivy				6 Months			No	

General Tree Assessment (Detailed)

Report selection criteria.

Projects.

The Brambles

--->
---> 1 year
---> 3 Months
---> 6 Months

Date Range.

Any Date

Work types.

----> Fell :: Fell to ground level
----> Further inspection :: Climb and inspect
----> Further inspection :: On internal trunk decay.
----> Ivy :: Sever/remove ivy
----> No action :: Unspecified
----> Reduce crown(s) :: By 20%
----> Reduce crown(s) :: By 25%
----> Re-inspect :: Once ivy removed
----> Re-inspect :: Unspecified
----> Remove :: Major dead wood
----> See Comment :: Unspecified

Latest Survey.

All surveys for the selected trees.
---> Last survey for each selected tree

Work Completed.

---> Work Completed
---> Work Not Completed

Number of trees in selected Project(s) 27

Number of trees in Report selection 27