25 January 2023 9:30 a.m.

Meeting with Highways Officer – Lyneham and Bradenstoke, SID Installation Review.

In Attendance: Martin Cook, Allison Bucknell, Frank Ball, Arthur Kingdon, and Elizabeth Martin

The group met to discuss the desired SID installations in locations across Lyneham and Bradenstoke.

<u>1st Meeting place – Slessor Road and A3102</u>

The group discussed the traffic issues found at this location and looked at a reasonable place to install a SID device. The picture below was agreed by Martin Cook as good place for installation and agreed that the current post in place requires replacement and could be a taller post to accommodate the SID unit. Good placement and would accommodate both directions of traffic.

Traffic Issue: 30mph zone

Issue of high rates of speed of vehicles as they approach and leave Lyneham.





What3words - ///capacity.catapult.fame

<u> 2nd Meeting place – Church Farm/A3102</u>

The group discussed the traffic issues found at this location and looked at a reasonable place to install a SID device.

The group discussed the traffic issues at this location. The picture below of the existing lamp post 13 was agreed to be an acceptable location for the installation of a SID device. Good placement and would accommodate both directions of traffic.

Traffic Issue: 30mph zone Issue of high rates of speed of vehicles.



What3words – ///prank.grapes.flux Lamp Post Number – 13

<u> 3rd Meeting place – Farthing Lane/A3102</u>

The group discussed the traffic issues found at this location such as speeds of vehicles as they come around the corner from both ways on this stretch of road. There was not an agreed suitable location for the devise to be placed and an interim solution might be to develop the verges into a wildflower meadow that does not get regularly cut back. Martin Cook and Allison Bucknell highlighted that area is undergoing significant changes with the new housing development underway and the structure of the road is likely to develop from that in the future. It was decided to put the decision for this location on hold until the development is completed, and a more accurate profile of traffic issues may be evidenced.



4th Meeting Place - Chippenham Road/B4069

The group discussed the traffic issues found at this location such as speeds of vehicles as they approach Lyneham and the round-about. It was acknowledged that there is a planned housing development coming to the area in the future.

The picture below of the existing lamp post 27 was agreed to be an acceptable location for the installation of a SID device. Good placement and would accommodate both directions of traffic.

Traffic Issue: 30mph zone??? Issue of high rates of speed of vehicles.



What3words - ///miss.plunger.unloads Lamp Post Number – 27

<u> 5th Meeting Place – Bradenstoke Village</u>

The group discussed the traffic issues in the village of Bradenstoke and it was recognised with the current issue of the B4069 the traffic conditions for Bradenstoke have changed and are unlikely to resume to a normal situation for at least the next 18 months. There are some questions over the required need for a SID installation in Bradenstoke as there are traffic variances that would require vehicles to reduce speed. One of the variances is how the road naturally becomes narrower due to off street parking. There is also a question of the light pollution that the SID would produce for residents in such a densely populated residential area. There was a discussion of a potential location on an existing lamp post, but concerns were raised about how access to the SID would be maintained. The road is narrow and there is very little room for suitable ladder safety measures to be ensured. An additional concern was shared that the location of this SID is not entirely suitable for both directions of traffic as the road bends and potentially would not provide the desired outcome for traffic calming.

Traffic Issue: 30mph zone

Issue of reported speed of vehicles, foot traffic safety, neighbourhood conditions, narrow roads.



What3words – ///skewed.joyously.sharpen Lamp Post Number - 7